



Product Discontinuation Notice: HN Series Relay Terminal Sockets

PDN.PG0003.06.11.2019

06.11.2019

Effective Date: Immediate

Last Time Buy Date: September 30, 2019

Last Eligible Ship Date: December 31, 2019

Discontinuation Details:

Before				
Item	Specifications			
Type	AHNA11	AHNA11P	AHNA21	AHNA21P
Contact arrangement	1 Form C		2 Form C	
Dielectric strength (Initial)	Between contact and coil		5,000Vrms for 1min. (Detection current: 10mA)	
Max. continuous current	16A	10A	5A	



After			
Item	Specifications		
Type	AHNA11K		AHNA21K
Contact arrangement	1 Form C		2 Form C
Dielectric strength (Initial)	Between contact and coil		4,000Vrms for 1min. (Detection current: 10mA)
Max. continuous current	10A		5A

Suggested Replacement:

Discontinued items	
No. of pole	Part number
1 pole	AHNA11
	AHNA11P
2 pole	AHNA21
	AHNA21P



Replacement items	
No. of pole	Part number
1 pole	AHNA11K
2 pole	AHNA21K

Affected Part Numbers: See Attached.

Datasheets: See Attached.

Notes: Panasonic announces the discontinuation and recommended replacement of certain HN Series Relay Terminal Socket part numbers. This will allow for more efficient product lineup integration.